



**JABATAN LAUT MALAYSIA**  
IBU PEJABAT LAUT  
PETI SURAT 12, JALAN LIMBUNGAN  
42007 PELABUHAN KLANG  
SELANGOR DARUL EHSAN



## NOTICE TO MARINERS

## NTM 190/2022

Telefon : 03-3346 7777 Emel : [kpgr@marine.gov.my](mailto:kpgr@marine.gov.my)  
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

---

Authority : Director of Marine, Malaysia

Position : Port Klang Waters

Charts Affected : MAL 5307  
BA 3945

---

### PORT KLANG NO 12 LIGHT BUOY RESTORED TO NORMAL PORT KLANG WATERS

---

Mariners are advised that Port Klang No 12 Light Buoy has been restored to normal.  
The details are as follows:

Name : Port Klang No 12  
Position : Lat. 03° 04.02' N  
Long. 101° 20.30' E  
Light Characteristics : Fl (2) R 10s

Mariners are advised to navigate with caution when in the vicinity.

This notice cancels NTM 187(T)/2022

**(EMIZUL FADLY BIN MASDEK)**  
for The Director General,  
Marine Department Malaysia.  
28<sup>th</sup> November 2022

---

*Safer Ships, Secure Ports, Cleaner Seas*



CERTIFIED TO ISO 9001:2015  
CERT. NO.: QMS 03602