



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 13(T)/2021

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : South China Sea

Charts Affected : MAL 6416
 BA 1374

TANJUNG BERHALA NORTH LIGHT BEACON UNRELIABLE KEMAMAN PORT, TERENGGANU

Mariners are advised that Tanjung Berhala North Light Beacon is unreliable. The details are as follows:

Name : Tanjung Berhala North

Position : Lat. 04° 13.056' N
 Long. 103° 31.076' E

Light Characteristic : Fl.(2)G.10s

Mariners are advised to navigate with caution in the area.

(RINA MASLINA BINTI BAHARUDIN)

for The Director General,
Marine Department Malaysia.

24th January 2021

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602