



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 38(T)/2022

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : South China Sea

Charts Affected : MAL 6416
 BA 1374

TANJUNG BERHALA NO.7 LIGHT BEACON UNRELIABLE KEMAMAN PORT, TERENGGANU

Mariners are advised that Tanjung Berhala No.7 Light beacon light is unreliable. The details are as follows:

Name : Tanjung Berhala No.7

Position : Lat. 04° 15.396' N
 Long. 103° 27.732' E

Light Characteristic : Q(1)G

Mariners are advised to navigate with caution in the area.

(EMIZUL FADLY BIN MASDEK)
for The Director General,
Marine Department Malaysia.
13th MARCH 2022

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602