



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 156/2022

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia
Position : Malacca Strait
Charts Affected : MAL 521 & MAL 54
 BA 3947, BA 3946 & BA 1358

PULAU UNDAN LIGHTHOUSE RESTORED TO NORMAL MALACCA STRAIT

Mariners are advised that Pulau Undan Lighthouse has been restored to normal.

Name : Pulau Undan
Position : Lat. 02° 02.900' N
 Long. 102° 20.100' E
Characteristic : FL (2).W.15S
Range/ Elevation : 18 Nm/ 53 Metre

Mariners are advised to navigate with caution.
This Notice cancels NTM 134(T)/2022

(EMIZUL FADLY BIN MASDEK)
for The Director General,
Marine Department Malaysia.
15th October 2022

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602