



**JABATAN LAUT MALAYSIA**  
IBU PEJABAT LAUT  
PETI SURAT 12, JALAN LIMBUNGAN  
42007 PELABUHAN KLANG  
SELANGOR DARUL EHSAN



## NOTICE TO MARINERS      NTM 145(T)/2022

Telefon           : 03-3346 7777    Emel            : [kpqr@marine.gov.my](mailto:kpqr@marine.gov.my)  
Faksimili        : 03-3168 5289    Laman Web   : <http://www.marine.gov.my>

---

Authority           : Director of Marine, Malaysia

Position           : Port Klang Waters

Charts Affected   : MAL 532  
                          BA 3946

---

### MAHANG 1 BUOY UNLIT PORT KLANG WATERS

---

Mariners are advised that Mahang 1 Buoy is unlit. The details are as follows:

Name                : Mahang 1  
Position            : Lat.    02° 52.60' N  
                          Long. 101° 16.31' E  
Light Characteristics   : Fl.G.2s

Mariners are advised to navigate with caution when in the vicinity.

**(MOHD IZUAN BIN ISNAN)**  
for The Director General,  
Marine Department Malaysia.  
27<sup>th</sup> September 2022

---

*Safer Ships, Secure Ports, Cleaner Seas*



CERTIFIED TO ISO 9001:2015  
CERT. NO.: QMS 03602