



**HYDROGRAPHIC OFFICE
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422
Website: www.marine.gov.my



BORNEO NORTH WEST COAST

176/2021(T) – PORT HAND BUOY, KUALA KEMENA, BINTULU – MISSING

Port Hand Buoy at position 03°11'29.503"N 113°01'33.515"E is reported missing.
Mariners are advised to navigate with caution when in vicinity.

Charts : SAR 401, SAR 402 & SAR 4001

Source : Sarawak Marine Department

Date : 23rd November 2021

" BERKHIDMAT UNTUK NEGARA "

[RADUAN BIN SERAP]

For Director of Marine Sarawak

"Safer Ships, Secure Ports, Cleaner Seas"



Cert. No: ISO 9001-0047621, ISO 9001-0047600