



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 124/2022

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia
Position : Malacca Straits
Charts Affected : MAL 521 & MAL 5123
 BA 2403

PIAI BUOY RESTORED TO NORMAL TANJUNG PELEPAS PORT, JOHOR

Mariners are advised that a Piai buoy has been restored to normal at Tanjung Pelepas Port, Johor. The details are as follows:

Name : Piai buoy
Position : Lat. 01° 14.280' N
 Long. 103° 29.730' E
Light Characteristic : FI(1)Y 5s

Mariners are advised to navigate with caution when in the vicinity.

This notice cancel NTM 103(T)/2022.

(Ts. MUHAMMAD FADHLI MAKHTAR)
for The Director General,
Marine Department Malaysia.
23rd August 2022

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602