



JABATAN LAUT MALAYSIA
 IBU PEJABAT LAUT WILAYAH SELATAN,
 81560 GELANG PATAH,
 JOHOR DARUL TA'ZIM



Tel : 07-5072313
 Faks : 07-5073679
 Laman Web : www.marine.gov.my
 Emel : pilwst@marine.gov.my

PEKELILING PELABUHAN NO. 20/2019
PORT CIRCULAR NO. 20/2019

DARIPADA : PENGARAH LAUT WILAYAH SELATAN
 FROM : DIRECTOR OF MARINE SOUTHERN REGION

KEPADA: SEMUA NAKHODA KAPAL, PELAUT, PEMILIK KAPAL & AGEN
 PERKAPALAN DAN MASYARAKAT PERKAPALAN AMNYA.
 TO: ALL SHIP MASTERS, MARINERS, SHIP OWNERS & AGENTS AND
 THE GENERAL SHIPPING COMMUNITY.

TARIKH/DATED : 11 Jun 2019 / 11 June 2019

**KERJA-KERJA MENYELAM BAGI MENCARI
 DAN MENGALIH SAUH DI DALAM
 KAWASAN LABUHAN, HAD PELABUHAN
 PASIR GUDANG, JOHOR**

**UNDERWATER WORKS TO RETRIEVE AND
 REMOVAL OF LOSS ANCHOR IN JOHOR PORT
 ANCHORAGE, PASIR GUDANG PORT LIMIT,
 JOHOR.**

Ini adalah untuk memaklumkan bahawa aktiviti-aktiviti menyelam akan dijalankan di dalam kawasan Labuhan, Had Pelabuhan Pasir Gudang dan butiran adalah sepertimana berikut:

This is to inform that underwater works will be carried out in the Johor Port Anchorage, Pasir Gudang Port Limit and the details are as follows:

Tempoh kerja ; 12 Jun 2019 - 15 Jun 2019

Duration ; 12 June 2019 - 15 June 2019

Waktu bekerja: Siang hari sahaja

Working hours: Daylight only

KAWASAN BEKERJA (WGS84):

WORKING AREA (WGS84):

	Latitud Utara	Longitud Timur
1	01° 18.54'	104° 06.84'

	Latitude North	Longitude East
1	01° 18.54'	104° 06.84'

“Ke Arah Negara Kelautan Elektronik”
 “Towards e-Maritime Nation”



PEKELILING PELABUHAN NO. 20/2019

PORT CIRCULAR NO. 20/2019

VESEL BEKERJA:

<u>Nama Vesel</u>	<u>Jenis Vesel</u>	<u>No. Lesen</u>
OPL MARINE LOGISTIC 17	Tunda	JPG000124T
OPL MARINE LOGISTIC 50	Kren Barj	JPG00358X

WORKING VESSEL:

<u>Nama Vesel</u>	<u>Jenis Vesel</u>	<u>No. Lesen</u>
OPL MARINE LOGISTIC 17	Towing	JPG000124T
OPL MARINE LOGISTIC 50	Crane Barge	JPG00358X

PERHATIAN

Semua vesel-vesel yang berlayar menghampiri kawasan diatas hendaklah membuat awasan rapi dan belayar dengan lebih berhati-hati.

Carta Terlibat : MAL 6130, BA 4044

Terima kasih.

CAUTION

Vessel navigating in the vicinity of that areas are required to keep a sharp lookout and navigate with extra caution.

Charts affected : MAL 6130, BA 4044

Thank you

Saya yang menandatangani amanah,



(HJ. DICKSON BIN DOLAH)
Pengarah Laut / *Director of Marine*
Jabatan Laut Malaysia
Marine Department Malaysia
Wilayah Selatan
Southern Region

“Ke Arah Negara Kelautan Elektronik”
“Towards e-Maritime Nation”



Cert. No: MAS 101138 (K)