



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 135(T)/2022

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia
Position : Malacca Strait
Charts Affected : MAL 554
 : BA 3944

PULAU RIMAU LIGHTHOUSE REDUCED POWER MALACCA STRAIT

Mariners are advised that Pulau Rimau Lighthouse is temporarily operating on reduced power and light nominal range is reduced to 15 nautical miles.

Name : Pulau Rimau Lighthouse
Position : Lat. 05° 14.680' N
 : Long. 100° 16.500' E
Characteristic : Fl.2.W.10s

Mariners are advised to navigate with caution.

This notice cancels NTM 133(T)/2022.

(Ts. MUHAMMAD FADHLI MAKHTAR)
for The Director General,
Marine Department Malaysia.
15th September 2022

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602