



**JABATAN LAUT MALAYSIA**  
IBU PEJABAT LAUT  
PETI SURAT 12, JALAN LIMBUNGAN  
42007 PELABUHAN KLANG  
SELANGOR DARUL EHSAN



## **NOTICE TO MARINERS      NTM 188(T)/2021**

Telefon           : 03-3346 7777   Emel            : [kpqr@marine.gov.my](mailto:kpqr@marine.gov.my)  
Faksimili        : 03-3168 5289   Laman Web   : <http://www.marine.gov.my>

---

Authority           : Director of Marine, Malaysia

Position           : South China Sea

Charts Affected   : MAL 635  
                          BA 3446 & BA 1379

---

### **KUANTAN PORT LEADING LIGHT 311° 04 REAR LIGHT BEACON UNLIT KUANTAN PORT, PAHANG**

Mariners are advised that Kuantan Port Leading Light 311° 04 Rear Light Beacon unlit.

Name                : Kuantan Port Leading Light 311° 04 Rear

Position            : Lat.    03° 58.940' N  
                          Long. 103° 25.490' E

Light Characteristic : OC.G.5s

Mariners are advised to navigate with caution in the area.

**(MOHD IZUAN BIN ISNAN)**  
for The Director General,  
Marine Department Malaysia.  
14<sup>th</sup> October 2021

---

*Safer Ships, Secure Ports, Cleaner Seas*



CERTIFIED TO ISO 9001:2015  
CERT. NO.: QMS 03602