



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 83(T)/2021

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia
Position : Malacca Strait
Charts Affected : MAL 521 & MAL 54
 BA 3947, BA 3946 & BA 1358

PULAU UNDAN LIGHTHOUSE RESTORED TO NORMAL MALACCA STRAIT

Mariners are advised that Pulau Undan Lighthouse has been restored to normal.

Name : Pulau Undan Lighthouse
Position : Lat. 02° 02.900' N
 Long. 102° 20.100' E
Characteristic : Fl.2.W.15s
Elevation : 53 m
Range : 15 nm
Structure : Red 8-sided concrete tower on building

This notice cancels NTM 74(T)/2021.

(MOHD FAIZAL BIN MOHD NASIR)
for The Director General,
Marine Department Malaysia.
28th April 2021

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602