



**HYDROGRAPHIC OFFICE
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422
Website: www.marine.gov.my



BORNEO NORTH WEST COAST

33/2023(T) – TANJUNG PO BUOYS RESTORED TO NORMAL

Mariners are advised that the following buoys have been restored to normal.

Name	Position	
	Latitude (N)	Longitude (E)
Buoy No. 5	01° 42' 19.247"	110° 33' 02.389"
Buoy No. 8	01° 40' 56.472"	110° 32' 36.312"
Buoy No. 11	01° 38' 59.200"	110° 30' 27.935"

2. Cancel NTM No. 15/2023(T) dated 6th February 2023 and No. 16/2023(T) and No. 17/2023(T) dated 10th February 2023.

Charts : SAR 12, SAR 13 & SAR 101
Source : Sarawak Region Marine Department
Date : 22nd March 2023

" BERKHIDMAT UNTUK NEGARA "

[MUHAMAD SAHABULLAH BIN KASIM]
For Director of Marine Sarawak

Safer Ships, Secure Ports, Cleaner Seas



Cert No: ISO 9001-0047600, ISO 9001-0047621