



**JABATAN LAUT MALAYSIA**  
**IBU PEJABAT LAUT**  
**PETI SURAT 12, JALAN LIMBUNGAN**  
**42007 PELABUHAN KLANG**  
**SELANGOR DARUL EHSAN**



## NOTICE TO MARINERS

**NTM 47/2022**

Telefon : 03-3346 7777 Emel : [kpgr@marine.gov.my](mailto:kpgr@marine.gov.my)  
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : South China Sea

Charts Affected : MAL 6436  
BA 1374

### **KERTIH PORT NO 2R LIGHT BUOY RESTORED TO NORMAL** **KERTIH PORT, TERENGGANU**

Mariners are advised that Kertih Port No.2R light buoy has been restored to normal.  
The details are as follows:

Name : Kertih Port No.2R Light Buoy  
Position : Lat. 04° 35.898' N, Long. 103° 27.678' E  
Light Characteristic : Q.R

This notice cancels NTM 21(T)/2022.

**(EMIZUL FADLY BIN MASDEK)**  
for The Director General,  
Marine Department Malaysia.  
29<sup>th</sup> MARCH 2022

*Safer Ships, Secure Ports, Cleaner Seas*



CERTIFIED TO ISO 9001:2015  
CERT. NO.: QMS 03602