



**HYDROGRAPHIC OFFICE  
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS  
(NOTIS PELAUT)**


TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422  
Website: www.marine.gov.my



**BORNEO NORTH WEST COAST**

**\*134/2021 – BATAM-SARAWAK INTERNET CABLE SYSTEM (BASICS) SUBMARINE SYSTEM**

Mariners are advised that PP Telecommunications Sdn Bhd will install submarine internet cable system for Batam-Sarawak Internet Cable System (BaSics) project at Malaysian Exclusive Economic Zone and offshore Sarawak on 12<sup>th</sup> September 2021 until 1<sup>st</sup> November 2021.

2. Insert submarine cables, , joining:

Point	Latitude	Longitude	Notes
96	1°15'49.980"N	104°25'56.040"E	In Malaysian Exclusive Economic Zone
97	1°15'54.660"N	104°25'57.660"E	
98	1°15'57.360"N	104°25'58.620"E	
99	1°16'00.840"N	104°26'01.980"E	
100	1°16'07.920"N	104°26'16.440"E	
101	1°16'26.220"N	104°26'51.060"E	
102	1°16'34.140"N	104°27'06.720"E	
103	1°16'40.500"N	104°27'19.320"E	
104	1°16'41.820"N	104°27'27.540"E	
105	1°16'48.840"N	104°27'45.780"E	
106	1°16'52.260"N	104°27'48.780"E	
107	1°16'53.940"N	104°27'48.840"E	
108	1°16'55.920"N	104°27'48.900"E	
109	1°17'02.940"N	104°27'51.960"E	
110	1°17'06.300"N	104°27'55.440"E	
111	1°17'10.320"N	104°28'07.440"E	
200	2°24'17.100"N	109°50'49.260"E	
201	2°23'51.240"N	109°53'17.940"E	
202	2°23'06.780"N	109°55'27.960"E	
203	2°22'14.940"N	109°56'42.840"E	
204	2°21'35.520"N	109°57'39.780"E	
205	2°20'47.640"N	109°58'21.120"E	
206	2°11'04.560"N	110°06'43.980"E	
207	2°00'04.680"N	110°16'13.080"E	
208	1°59'19.740"N	110°16'51.840"E	
209	1°54'07.260"N	110°22'42.120"E	
210	1°53'08.580"N	110°23'13.980"E	
211	1°53'08.040"N	110°23'14.280"E	
212	1°46'59.220"N	110°23'51.660"E	
213	1°46'36.600"N	110°23'55.200"E	
214	1°46'22.980"N	110°23'52.020"E	
215	1°46'21.120"N	110°23'50.940"E	
216	1°45'57.960"N	110°23'37.320"E	

**“Safer Ships, Secure Ports, Cleaner Seas”**



Cert. No: ISO 9001-0047621, ISO 9001-0047600



**HYDROGRAPHIC OFFICE  
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS  
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422  
Website: www.marine.gov.my



217	1°44'58.860"N	110°22'57.480"E	In Malaysian Territorial Waters
218	1°44'58.020"N	110°22'56.940"E	
219	1°44'31.620"N	110°22'37.380"E	
220	1°44'17.520"N	110°22'26.940"E	
221	1°44'08.280"N	110°22'20.100"E	
222	1°43'52.680"N	110°22'07.320"E	
223	1°43'00.000"N	110°21'24.120"E	
224	1°42'58.560"N	110°21'22.980"E	
225	1°42'52.560"N	110°21'18.300"E	
226	1°42'51.900"N	110°21'17.760"E	
227	1°42'47.820"N	110°21'15.480"E	

*Positions in WGS 84 Datum*

3. Vessels involved:

Name	Flag	Length	Breadth
LIMIN HANDLER	Indonesia	33.02 m	10.40 m
LIMIN VENTURE	Indonesia	122.85 m	19.38 m

4. Mariners are advised to navigate with caution when in vicinity and update their affected charts accordingly.

Charts : SAR 1, SAR 2, SAR 3, SAR 5, SAR 11, SAR 45, SAR 113 & SAR 123

Source : WESTEXT SDN BHD

Date : 7<sup>th</sup> September 2021

**" BERKHIDMAT UNTUK NEGARA "**

**[ RADUAN BIN SERAP ]**  
For Director of Marine Sarawak

**"Safer Ships, Secure Ports, Cleaner Seas"**



Cert. No: ISO 9001-0047621, ISO 9001-0047600