



**HYDROGRAPHIC OFFICE  
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS  
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422  
Website: [www.marine.gov.my](http://www.marine.gov.my)



**BORNEO NORTH WEST COAST**

**15/2023(T) – BUOY NO. 5, TANJUNG PO - MISSING**

Buoy No. 5, Tanjung Po 01°42'19.5"N 110°33'02.4"E is reported missing. Mariners are advised to navigate with caution in the area.

Charts : SAR 12, SAR 13 & SAR 101  
Source : Sarawak Region Marine Department  
Date : 6<sup>th</sup> February 2023

**"BERKHIDMAT UNTUK NEGARA"**

**[ RADUAN BIN SERAP ]**

For Director of Marine Sarawak

***Safer Ships, Secure Ports, Cleaner Seas***



Cert No: ISO 9001-0047600, ISO 9001-0047621