



**HYDROGRAPHIC OFFICE  
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS  
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422  
Website: [www.marine.gov.my](http://www.marine.gov.my)



**BORNEO NORTH WEST COAST**

**22/2023(T) – PORT LATERAL MARK - SIP 6 BUOY, SAMALAJU PORT - MISSING**

Port Lateral Mark – SIP 6 buoy, Samalaju Port 03°35'45.700"N 113°17'46.300"E is reported missing. Mariners are advised to navigate with caution in the area.

Charts : SAR 501 & SAR 5001  
Source : Sarawak Region Marine Department  
Date : 2<sup>nd</sup> March 2023

**"BERKHIDMAT UNTUK NEGARA"**

[ RADUAN BIN SERAP ]  
For Director of Marine Sarawak

***Safer Ships, Secure Ports, Cleaner Seas***



Cert No: ISO 9001-0047600, ISO 9001-0047621