



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS

NTM 197/2022

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia
Position : Malacca Strait
Charts Affected : MAL 532, MAL 540 & MAL54
BA 1143

NEW LIGHT BUOY ESTABLISHED IN POSITION MALACCA STRAITS

Mariners are advised that new light buoy have been established in position in Malacca Strait:

Name : Batuan Penyu
Position : Lat. 03° 13.740' N,
Long. 101° 12.680' E
Range : 5 Nm
Light Characteristic : Q(9).5S
Type : West Cardinal Mark

Mariners are advised to take extra caution when navigating in the vicinity.

(MOHD IZUAN BIN ISNAN)
for The Director General,
Marine Department Malaysia.
2th December 2022

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602