



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 68(T)/2022

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : South China Sea

Charts Affected : MAL 6359
 BA 3446 & BA 1379

KUANTAN PORT LEADING LIGHT 311° 04 REAR LIGHT BEACON UNLIT KUANTAN PORT, PAHANG

Mariners are advised that Kuantan Port Leading Light 311° 04 Rear Light Beacon unlit.

Name : Kuantan Port Leading Light 311° 04 Rear

Position : Lat. 03° 58.940' N
 Long. 103° 25.490' E

Light Characteristic : Oc.G.5s

Mariners are advised to navigate with caution in the area.

(EMIZUL FADLY BIN MASDEK)
for The Director General,
Marine Department Malaysia.
19th May 2022

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602