



**JABATAN LAUT MALAYSIA**  
IBU PEJABAT LAUT  
PETI SURAT 12, JALAN LIMBUNGAN  
42007 PELABUHAN KLANG  
SELANGOR DARUL EHSAN



## NOTICE TO MARINERS      NTM 55(T)/2023

Telefon           : 03-3346 7777    Emel               : [kpqr@marine.gov.my](mailto:kpqr@marine.gov.my)  
Faksimili        : 03-3168 5289    Laman Web      : <http://www.marine.gov.my>

---

Authority           : Director of Marine, Malaysia

Position           : Malacca Waters

Charts Affected   : MAL 5217  
                          BA 3946, BA 1141

---

### SUNGAI UDANG NO 2 LIGHT BUOY UNLIT MALACCA WATERS

---

Mariners are advised that Sungai Udang No 2 light buoy is unlit.

Name                : Sungai Udang No. 2

Position            : Lat.    02° 15.030' N  
                          Long. 102° 06.426' E

Light Characteristic : Q.R

Mariners are advised to navigate with caution when in the vicinity.

**(EMIZUL FADLY BIN MASDEK)**

for The Director General,  
Marine Department Malaysia.

13<sup>th</sup> April 2023

---

*Safer Ships, Secure Ports, Cleaner Seas*



CERTIFIED TO ISO 9001:2015  
CERT. NO.: QMS 03602