



**JABATAN LAUT MALAYSIA**  
IBU PEJABAT LAUT  
PETI SURAT 12, JALAN LIMBUNGAN  
42007 PELABUHAN KLANG  
SELANGOR DARUL EHSAN



## NOTICE TO MARINERS      NTM 51/2023

Telefon           : 03-3346 7777    Emel               : [kpqr@marine.gov.my](mailto:kpqr@marine.gov.my)  
Faksimili        : 03-3168 5289    Laman Web      : <http://www.marine.gov.my>

---

Authority           : Director of Marine, Malaysia

Position           : Kuantan Port, Pahang

Charts Affected   : MAL 6359  
                          BA 3446

---

### NDWT BREAKWATER 5Y LIGHT BEACON RESTORED TO NORMAL KUANTAN WATERS, PAHANG

---

Mariners are advised that NDWT Breakwater 5Y Light Beacon has been restored to normal. Details are as follows:

Name                :       NDWT Breakwater 5Y  
Position            :       Lat.     3° 58.920' N  
                          Long. 103° 26.787' E  
Light Characteristic :       Fl.Y.5s

Mariners are advised to navigate with caution when in the vicinity.  
This notice cancels NTM 46(T)/2023.

**(EMIZUL FADLY BIN MASDEK)**  
for The Director General,  
Marine Department Malaysia.  
12<sup>th</sup> April 2023

---

*Safer Ships,*  *Smarter Seas*

CERTIFIED TO ISO 9001:2015  
CERT. NO.: QMS 03602