



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 40/2023

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Lumut, Perak

Charts Affected : MAL 5416
 BA 792

REPOSITION DINDING 1R LUMUT, PERAK

Mariners are advised that DINDING 1R light bouy has been reposition in Lumut, Perak.

Name : DINDING 1R
Position : Lat. 04° 15.134' N
 Long. 100° 35.530' E
Range of Light : 5 Nm
Light Characteristic : Fl.(2).R. 10S
Description : Port hand

Mariners are advised to navigate with caution when in the vicinity.

(MOHD IZUAN BIN ISNAN)
for The Director General,
Marine Department Malaysia.
30th March 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602