



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 53(T)/2023

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia
Position : South China Sea, Kuala Rompin
Charts Affected : MAL 635
 BA 3445

BATUAN PONTIAN LIGHT BEACON UNLIT SOUTH CHINA SEA

Mariners are advised that Batuan Pontian light beacon is unlit.

Name : Batuan Pontian
Position : Lat. 02° 45.378' N
 Long. 103° 36.688' E
Light Characteristic : Fl.W.5s

Mariners are advised to navigate with caution when in the vicinity.

(EMIZUL FADLY BIN MASDEK)
for The Director General,
Marine Department Malaysia.
12th April 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602