



**JABATAN LAUT MALAYSIA**  
IBU PEJABAT LAUT  
PETI SURAT 12, JALAN LIMBUNGAN  
42007 PELABUHAN KLANG  
SELANGOR DARUL EHSAN



## **NOTICE TO MARINERS      NTM 39(T)/2023**

Telefon : 03-3346 7777 Emel : [kpgr@marine.gov.my](mailto:kpgr@marine.gov.my)  
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

---

Authority : Director of Marine, Malaysia

Position : Lumut, Perak Waters

Charts Affected : MAL 5425  
BA 3944

---

### **VALE NO.2 LIGHTBOUY DAMAGE LUMUT WATERS**

---

Mariners are advised that Vale No.2 Lightbouy is damage and unlit.

Name : Vale No.2

Position : Lat. 04° 09.119' N  
Long. 100° 33.669' E

Light Characteristic : Oc(2+1).R.15s

Mariners are advised to navigate with caution when in the vicinity.

**(EMIZUL FADLY MASDEK)**  
for The Director General,  
Marine Department Malaysia.  
27<sup>th</sup> March 2023

---

*Safer Ships, Secure Ports, Cleaner Seas*



CERTIFIED TO ISO 9001:2015  
CERT. NO.: QMS 03602