



**HYDROGRAPHIC OFFICE
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422
Website: www.marine.gov.my



BORNEO NORTH WEST COAST

39/2023(T) – TANJUNG PO, BUOY NO. 2 - MISSING

Buoy No. 2 at position 01° 48' 09.970"N, 110° 30' 59.022"E is reported missing.

2. Mariners are advised to navigate with caution in the area.

Charts : SAR 12, SAR 13 & SAR 101
Source : Sarawak Region Marine Department
Date : 28th March 2023

" BERKHIDMAT UNTUK NEGARA "

[MUHAMAD SAHABULLAH BIN KASIM]

For Director of Marine Sarawak

Safer Ships, Secure Ports, Cleaner Seas



Cert No: ISO 9001-0047600, ISO 9001-0047621