



**JABATAN LAUT MALAYSIA**  
**IBU PEJABAT LAUT**  
**PETI SURAT 12, JALAN LIMBUNGAN**  
**42007 PELABUHAN KLANG**  
**SELANGOR DARUL EHSAN**



## **NOTICE TO MARINERS      NTM 43(T)/2023**

Telefon           : 03-3346 7777    Emel               : [kpgr@marine.gov.my](mailto:kpgr@marine.gov.my)  
Faksimili       : 03-3168 5289    Laman Web      : <http://www.marine.gov.my>

---

Authority           : Director of Marine, Malaysia  
Position           : Pengerang, Johor Waters.  
Charts Affected   : MAL 6124, MAL 515  
                          BA 2403

---

### **POH LAI LIGHT BUOY OFF STATION JOHOR WATERS**

---

Mariners are advised that an Isolated danger mark light buoy is off station. The details are as follows:

Name               : Poh Lai  
Position           : **Lat.     01° 17.730' N,**  
                          **Long. 104° 11.202' E**  
Light Characteristic   : Fl. (2).W.10s  
Type of Mark       : **Isolated Danger Mark**

Mariners are advised to navigate with caution when in the vicinity

**(EMIZUL FADLY BIN MASDEK)**  
for The Director General,  
Marine Department Malaysia.  
1<sup>st</sup> April 2023

---

*Safer Ships, Secure Ports, Cleaner Seas*



CERTIFIED TO ISO 9001:2015  
CERT. NO.: QMS 03602