



**HYDROGRAPHIC OFFICE
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422
Website: www.marine.gov.my



BORNEO NORTH WEST COAST

94/2023(T) – NO. 8 BUOY AND BATU TIONG BUOY, TANJUNG PO – OFF STATION

Mariners are advised that No. 8 Buoy and Batu Tiong Buoy are reported off station and drifting. The details are as follows:

Navigation Aid	Charted actual position	Current location spotted drifting
No. 8 Buoy Fl.R.5s	01°40'57.300"N 110°32'36.000"E	01°40'0.80"N 110°31'46.20"E
Batu Tiong Buoy Fl(2)6s	01°38'52.226"N 110°30'12.950"E	01°38'51.80"N 110°30'11.80"E

2. Mariners are advised to navigate with caution in the area.

Charts : SAR 12, SAR 13 & SAR 101

Source : Sarawak Region Marine Department

Date : 20th June 2023

"BERKHIDMAT UNTUK NEGARA"

[ABDUL AZIZ BIN ABDUL MAJID]

For Director of Marine Sarawak

Safer Ships, Secure Ports, Cleaner Seas



Cert No: ISO 9001-0047600, ISO 9001-0047621