



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUATERS
P.O BOX 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN
MALAYSIA



PENINSULAR NOTICE TO MARINERS NTM 163/2023

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : South China Sea

Charts Affected : MAL 635
BA 3445

**KUALA NENASI LIGHT BUOY RESTORED TO NORMAL
SOUTH CHINA SEA**

Mariners are advised that Kuala Nenasi Light Buoy has been restored to normal:

Name : Kuala Nenasi

Position : Lat. 03° 04.320' N
Long. 103° 27.450' E

Light Characteristic : LFI.W.10s

Mariners are advised to navigate with caution when in the vicinity.

This notice cancels NTM 132(T)/2023

(MOHD IZUAN BIN ISNAN)
for The Director General,
Malaysia Marine Department
18th July 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 900:2015
CERT. NO.: QMS 03602