



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUATERS
P.O BOX 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN
MALAYSIA



PENINSULAR NOTICE TO MARINERS NTM 147(T)/2023

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia
Position : Pulau Tioman, South China Sea
Charts Affected : MAL 6257
BA 3445

**MARINA TIOMAN BREAKWATER STARBOARD LIGHT BEACON UNLIT
SOUTH CHINA SEA**

Mariners are advised that Marina Tioman Breakwater Starboard light beacon is unlit.
Details are as follows:

Name : Marina Tioman Breakwater Starboard
Position : Lat. 02° 49.126' N
Long. 104° 09.376' E
Light Characteristic : Q.G

Mariners are advised to navigate with caution when in the vicinity.

(EMIZUL FADLY MASDEK)
for The Director General,
Malaysia Marine Department
1st July 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602