



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUATERS
P.O BOX 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN
MALAYSIA



PENINSULAR NOTICE TO MARINERS NTM 152/2023

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : South China Sea

Charts Affected : MAL 6359
BA 3445

**SUNGAI KUANTAN WRECK LIGHT BUOY RE-ESTABLISHED IN POSITION
SOUTH CHINA SEA**

Mariners are advised that Sungai Kuantan Wreck Light Buoy has been re-established in position:

Name : Sungai Kuantan Wreck Light buoy
Position : Lat. 03° 47.450' N
Long. 103° 21.157' E
Light Characteristic : Fl.Y.5s

Mariners are advised to navigate with caution when in the vicinity.

This notice cancels NTM 133T/2021.

(MOHD IZUAN BIN ISNAN)
for The Director General,
Malaysia Marine Department
12th July 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 900:2015
CERT. NO.: QMS 03602