



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



PENINSULAR NOTICE TO MARINERS NTM 175T/2022

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Kertih, Terengganu

Charts Affected : Mal 6441
BA 3482

PATON BANK LIGHT BUOY UNLIT
KERTIH, TERENGGANU WATERS

Mariners are advised that Paton Bank light buoy is unlit. The details are as follows:

1. Name : Paton Bank
Position : Lat. 04° 32.670' N, Long. 103° 31.370' E
Light Characteristic : FL.R.5S

Mariners are advised to navigate with caution in the area.

(Ts. MUHAMMAD FADHLI BIN MAKHTAR)
for The Director General,
Marine Department Malaysia.
6th August 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602