



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



PENINSULAR NOTICE TO MARINERS - NTM 158/2023

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia
Position : South China Sea, Kuantan Port
Charts Affected : MAL 6359
BA 3446 & BA 1379

KUANTAN PORT LEADING LIGHT 311° 14' FRONT LIGHT BEACON RESTORED TO NORMAL PAHANG WATERS

Mariners are advised that Kuantan Port Leading Light 311° 14' Front Light beacon has been restored to normal:

Name : Kuantan Port Leading Light 311° 14' Front
Position : Lat. 03° 58.592' N
Long. 103° 25.887' E
Light Characteristic : Q.G

Mariners are advised to navigate with caution in the area.

This notice cancels NTM 73(T)/2023

(MOHD IZUAN BIN ISNAN)
for The Director General,
Marine Department Malaysia.
13th July 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602