



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUATERS
P.O BOX 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN
MALAYSIA



PENINSULAR NOTICE TO MARINERS NTM 205(T)/2023

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia
Position : South China Sea, Tioman Island
Charts Affected : MAL 625, MAL 6257
 BA 3445

PULAU TOKONG BAHARA LIGHT BEACON UNLIT
SOUTH CHINA SEA

Mariners are advised that Pulau Tokong Bahara light beacon is unlit. The details are as follows:

Name : **Pulau Tokong Bahara**
Position : **Lat. 02° 40.031' N, Long. 104° 03.747' E**
 (*Datum: WGS-84*)
Light Characteristic : **L.FI.W.15s**

Mariners are advised to navigate with caution when in the vicinity.

(EMIZUL FADLY BIN MASDEK)
for The Director General,
Marine Department Malaysia.
11th September 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 900:2015
CERT. NO.: QMS 03602