



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUATERS
P.O BOX 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN
MALAYSIA



PENINSULAR NOTICE TO MARINERS NTM 213 /2023

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Lumut, Perak

Charts Affected : MAL 5416
BA 792

**DINDING 3R LIGHT BUOY RESTORED TO NORMAL
PERAK WATER**

Mariners are advised that Dinding 3R Light Buoy has been restored to normal. Details are as follows:

Name : Dinding 3R
Position : Lat. 04° 14.441' N
Long. 100° 37.180' E
Light Characteristic : Q.R

Mariners are advised to navigate with caution when in the vicinity.

This Notice cancels NTM 145(T)/2023.

(EMIZUL FADLY MASDEK)
for The Director General,
Malaysia Marine Department
17th September 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 900:2015
CERT. NO.: QMS 03602