



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



PENINSULAR NOTICE TO MARINERS - NTM 190/2023

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia
Position : South China Sea, Kemaman Port
Charts Affected : MAL 6416
BA 1374

**KEMAMAN BREAKWATER NORTH LIGHT BEACON RESTORED TO NORMAL
TERENGGANU WATERS**

Mariners are advised that Kemaman Breakwater North light beacon has been restored to normal.

Name : Kemaman Breakwater North
Position : Lat. 04° 13.991' N
Long. 103° 27.233' E
Light Characteristic : Q.R

Mariners are advised to navigate with caution in the area.

(EMIZUL FADLY MASDEK)
for The Director General,
Marine Department Malaysia.
20th August 2023.

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602