



JABATAN LAUT MALAYSIA
MALAYSIA MARINE DEPARTMENT
MARINE HEADQUARTERS
P.O BOX 12, JALAN LIMBUNGAN
42007 PORT KLANG
SELANGOR DARUL EHSAN
MALAYSIA



Tel : 603-3346 7777
Faks : 603-3168 5289
Laman Web : www.marine.gov.my

SABAH NOTICE TO MARINERS - NTM 12 (T) / 2023

Authority : Director of Marine, Malaysia
Position : Sabah Waters, Malaysia
Charts Affected : MAL 8433 , MAL 8434
BA 4418

BEACONS AT TERUSAN TANDO BULONG SEMPORNA WATERS DAMAGED AND UNLIT

Mariners are informed that Beacons at Terusan Tando Bulong Semporna are reported damaged and unlit. Details of the particular beacons are as follow:

LOCATION	NAME OF BEACON	GEOGRAPHIC COORDINATES (WGS 84)	
		LATITUDE	LONGITUDE
PULAU GUSUNGAN	NO.1 GUSUNGAN REEF(G)	04° 18' 07" N	118° 33' 11" E
BETWEEN PULAU GUSUNGAN AND PULAU MANAMPILIK	NO.2 (GREEN)	04° 21' 41" N	118° 33' 30" E
BARAT PULAU MANAMPILIK	NO.3 (GREEN)	04° 21' 29" N	118° 34' 34" E
TIMUR TANJUNG PERAPAT	NO.4 (RED)	04° 22' 41" N	118° 34' 32" E
BARAT PULAU SIPANGGAU	NO.5 (GREEN)	04° 22' 37" N	118° 35' 33" E
TIMUR KAMPUNG KABOGAN	NO.8 (GREEN)	04° 23' 03" N	118° 37' 08" E
TIMUR KG KABONGAN	NO.12 (GREEN)	04° 23' 43" N	118° 37' 52" E
TIMUR KG KABONGAN	NO.10 (RED)	04° 23' 48" N	118° 37' 04" E
SELATAN PULAU SEBANGKAT	NO.33 (RED)	04° 31' 47" N	118° 39' 08" E
SELATAN PULAU LARAPAN	NO.29 (GREEN)	04° 30' 29" N	118° 36' 26" E

Mariners are advised to navigate with caution when in the vicinity.

(MUHAMMAD ZAKWAN BIN ZAHARI)

For The Director of Marine

Malaysia Marine Department

05TH MAY 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015 CERT. NO.: QMS 03602