



**MALAYSIA MARINE DEPARTMENT**  
**MARINE HEADQUATERS**  
**P.O BOX 12, JALAN LIMBUNGAN**  
**42007 PELABUHAN KLANG**  
**SELANGOR DARUL EHSAN**  
**MALAYSIA**



**PENINSULAR NOTICE TO MARINERS NTM 253(T)/2023**

Telefon : 03-3346 7777 Emel : [kpqr@marine.gov.my](mailto:kpqr@marine.gov.my)  
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

---

Authority : Director of Marine, Malaysia  
Position : South China Sea, Pulau Tioman  
Charts Affected : MAL 635  
BA 3445

---

**AIR LELEH UTARA LIGHTBUOY UNLIT**  
**PULAU TIOMAN KUANTAN WATERS**

---

Mariners are advised that Air Leleh Utara Light buoy is unlit. The details are as follows:

**Name : Air Leleh Utara**  
**Position : Lat. 03° 36.180' N**  
**Long. 103° 27.180' E**  
**Light Characteristic: Fl.Y.10s**

Mariners are advised to navigate with caution when in the vicinity.

**(EMIZUL FADLY MASDEK)**  
for The Director General,  
Malaysia Marine Department  
26<sup>th</sup> October 2023