



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUATERS
P.O BOX 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN
MALAYSIA



PENINSULAR NOTICE TO MARINERS NTM 250/2023

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia
Position : South China Sea, Kerteh Port
Charts Affected : MAL 6441
BA 3482

**KUALA BARU KERTIH LIGHT BEACON RESTORED TO NORMAL
TERENGGANU WATERS**

Mariners are advised that Kuala Baru Kertih light beacon has been restored to normal.
Details are as follows:

Name : Kuala Baru Kertih
Position : Lat. 04° 30.895' N
Long. 103° 27.354' E
Light Characteristic : FL(2).W.5s

Mariners are advised to navigate with caution when in the vicinity.

This notice cancel NTM 239(T)/ 2023

(Ts. MUHAMMAD FADHLI BIN MAKHTAR)
for The Director General,
Malaysia Marine Department
22nd October 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 900:2015