



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUARTERS
P.O BOX 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN
MALAYSIA



PENINSULAR NOTICE TO MARINERS NTM 248/2023

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Johor waters

Charts Affected : MAL 5123, MAL 5128
 BA 4038

PTP PATCH LIGHTBUOY PERMANENTLY WITHDRAWN
JOHOR WATERS

Mariners are advised that PTP Patch light buoy is permanently withdrawn. The details are as follows:

Name : PTP PATCH

Position : Lat. 01° 15.273' N
 Long. 103° 33.542' E
(Above Coordinates are referenced to Datum: WGS-84)

Range of Light : 5 Nm

Light Character : FL(4)Y10S

Description : Special Mark

Mariners are advised to navigate with caution when in the vicinity.

(Ts. MUHAMMAD FADHLI BIN MAKHTAR)
for The Director General,
Marine Department Malaysia.
19th October 2023