



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUATERS
P.O BOX 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN
MALAYSIA



PENINSULAR NOTICE TO MARINERS NTM 258/2023

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Perak Waters, Lumut

Charts Affected : MAL 5425
BA 3944

**VALE NO.5 LIGHT BUOY REPLACED IN POSITION
PERAK WATER**

Mariners are advised that Vale No. 5 light buoy has been replaced in position. Details are as follows:

Name : **Vale No.5**
Position : **Lat. 04° 09.029' N**
Long. 100° 35.100' E
Light Characteristic : **Oc (2+1).G.15s**

Mariners are advised to navigate with caution when in the vicinity.

This Notice cancels NTM 176(T)/2023.

(EMIZUL FADLY MASDEK)
for The Director General,
Malaysia Marine Department
3rd November 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602