



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUARTERS
P.O BOX 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN
MALAYSIA



PENINSULAR NOTICE TO MARINERS NTM 259/2023

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Port Kelang, Selangor

Charts Affected : MAL 532
 BA 8232

**SIR 1 & SIR 2 LIGHT BUOY PERMANENTLY WITHDRAWN
PORT KELANG**

Mariners are advised that a temporary Special Mark Buoy SIR 1 & SIR 2 is permanently withdrawn from Port Kelang waters. The details are as follows:

Name	:	SIR 1
Position	:	Lat. 02° 59.920' N Long. 101° 22.740' E
Light Character	:	Fl.Y.5s
Description	:	Special Mark (Yellow)
Name	:	SIR 2
Position	:	Lat. 03° 01.170' N Long. 101° 20.640' E
Light Character	:	Fl.Y.5s
Description	:	Special Mark (Yellow)

Mariners are advised to navigate with caution. This Notice cancels NTM 198(T)/2023 & NTM 197(T)/2023.

(EMIZUL FADLY MASDEK)
for The Director General,
Malaysia Marine Department
3rd November 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602