



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 55(T)/2023

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Malacca Waters

Charts Affected : MAL 5217
 BA 3946, BA 1141

SUNGAI UDANG NO 2 LIGHT BUOY UNLIT MALACCA WATERS

Mariners are advised that Sungai Udang No 2 light buoy is unlit.

Name : Sungai Udang No. 2

Position : Lat. 02° 15.030' N
 Long. 102° 06.426' E

Light Characteristic : Q.R

Mariners are advised to navigate with caution when in the vicinity.

(EMIZUL FADLY BIN MASDEK)

for The Director General,
Marine Department Malaysia.

13th April 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602