



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS

NTM 78(T)/2023

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Kelantan Waters

Charts Affected : MAL 664
BA 3446

TOK BALI PORT LIMIT NO. 1 LIGHTBUOY UNLIT KELANTAN

Mariners are advised that Tok Bali Port Limit No.1 Light Buoy is unlit. The details are as follows: -

Name : Tok Bali Port Limit No. 1
Position : Lat. 05° 57.800' N
Long. 102° 30.110' E
Light Characteristic : Fl.Y.5s

Mariners are advised to navigate with caution in the area.

(MOHD IZUAN BIN ISNAN)
for The Director General,
Malaysia Marine Department
2th May 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602