



**MALAYSIA MARINE DEPARTMENT**  
**MARINE HEADQUARTERS**  
**PO BOX 12, JALAN LIMBUNGAN**  
**42007 PELABUHAN KLANG**  
**SELANGOR DARUL EHSAN**



**PENINSULAR NOTICE TO MARINERS      NTM 05(T)/2024**

Telefon           : 03-3346 7777    Emel               : [kpqr@marine.gov.my](mailto:kpqr@marine.gov.my)  
 Faksimili       : 03-3168 5289    Laman Web      : <http://www.marine.gov.my>

Authority           : Director of Marine, Malaysia

Position           : Malacca Straits

Charts Affected   : MAL 565 & MAL 54  
                           BA 3943 & BA 3947

**CABLE INSTALLATION (IAX) PHASE 4  
 MALACCA STRAITS**

Mariners are advised that cable installation works for India-Asia-Express (IAX) Phase 4 will be carried out by OMS Group Sdn Bhd.

Duration: **3<sup>rd</sup> January - 30<sup>th</sup> March 2024**

Vessels Involve:

| Name        | Type        | Flag            | Call Sign |
|-------------|-------------|-----------------|-----------|
| CS Resolute | Cable Layer | Marshall Island | V7FF3     |
| TB Sueann   | Tug         | Malaysia        | 9MWB3     |

Area: The work area is enclosed by an imaginary lines connecting the following points :

| Point<br>( Kedah Waters) | Latitude      | Longitude     |
|--------------------------|---------------|---------------|
| 1                        | 06° 38.322' N | 97° 56.447' E |
| 2                        | 06° 35.315' N | 97° 57.699' E |
| 3                        | 06° 35.143' N | 97° 57.798' E |
| 4                        | 06° 04.060' N | 98° 15.851' E |
| 5                        | 06° 03.918' N | 98° 15.920' E |

|    |               |               |
|----|---------------|---------------|
| 6  | 06° 03.263' N | 98° 16.158' E |
| 7  | 06° 01.918' N | 98° 16.764' E |
| 8  | 05° 53.340' N | 98° 20.530' E |
| 9  | 05° 53.212' N | 98° 20.575' E |
| 10 | 05° 35.437' N | 98° 33.669' E |
| 11 | 05° 08.184' N | 98° 54.167' E |
| 12 | 04° 47.378' N | 99° 09.062' E |

| Point<br>( Johor Waters) | Latitude      | Longitude      |
|--------------------------|---------------|----------------|
| 1                        | 01° 57.647' N | 102° 17.511' E |
| 2                        | 01° 54.681' N | 102° 23.337' E |
| 3                        | 01° 51.837' N | 102° 30.001' E |
| 4                        | 01° 49.560' N | 102° 34.778' E |
| 5                        | 01° 44.598' N | 102° 46.608' E |
| 6                        | 01° 35.280' N | 103° 04.217' E |
| 7                        | 01° 26.464' N | 103° 14.175' E |
| 8                        | 01° 19.065' N | 103° 21.370' E |
| 9                        | 01° 17.657' N | 103° 22.701' E |
| 10                       | 01° 15.236' N | 103° 25.127' E |

*Above coordinates are referenced to Datum: WGS-84*

Mariners are advised to navigate with caution when in the vicinity and keep clear of the working area.

**(EMIZUL FADLY MASDEK)**  
for The Director General,  
Malaysia Marine Department.  
3<sup>rd</sup> January 2024