



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUARTERS, MENARA DIUS API
P.O BOX 664, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS

NTM 152/2024

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Malacca Strait

Charts Affected : MAL 521
BA 3947

BUKIT SEGENTING LIGHTHOUSE RESTORED TO NORMAL MALACCA STRAIT

Mariners are advised that Bukit Segenting lighthouse has been restored to normal. The details are as follows:

Name	: Bukit Segenting
Position	: Lat. 01° 47.5' N Long. 102° 57.1' E (Datum: WGS-84)
Elevation	: 86 m
Characteristic	: FI (4)W 30s

Mariners are advised to navigate with caution when in the vicinity.

(EMIZUL FADLY MASDEK)
for The Director General,
Malaysia Marine Department.
11th August 2024.