



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUATERS
P.O BOX 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN
MALAYSIA



PENINSULAR NOTICE TO MARINERS NTM 163 / 2024

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Johor Waters

Charts Affected : MAL 6134
 : BA 2403

BC 2 LIGHTBUOY RE-PLACED IN POSITION
JOHOR WATERS

Mariners are advised that BC 2 lightbuoy has been re-placed in position. The details are as follows:

Name : **BC 2**

Position : **Lat. 01° 26.216' N**
Long. 104° 03.938' E
(Datum: WGS-84)

Light Characteristic : **Q.W**

Mariners are advised to navigate with caution when in the vicinity.
This notice cancels NTM 123(T)/2024.

(EMIZUL FADLY MASDEK)
for The Director General,
Malaysia Marine Department.
23rd August 2024