



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUARTERS
P.O BOX 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN
MALAYSIA



PENINSULAR NOTICE TO MARINERS NTM 175/2024

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia
Position : South China Sea, Terengganu
Charts Affected : MAL 664
 BA 3447

**UNION STAR WRECK BUOY RE-PLACED IN POSITION
TERENGGANU WATERS**

Mariners are advised that Union star wreck buoy has been repositioned.

Details are as follows:

Name : **UNION STAR WRECK**
Position : **Lat. 05° 52.791' N**
 Long. 102° 38.379' E
Light Character : **FL(2).W.10S**
Description : **Isolated danger**

Mariners are advised to keep clear of the wreck and navigate with caution when in the vicinity.

This notice cancels/supersede NTM 110(T)/2024.

(TS MUHAMMAD FADHLI BIN MAKHTAR)

for The Director General,
Malaysia Marine Department
10th September 2024