



PENINSULAR NOTICE TO MARINERS NTM 175T/2022

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Kertih, Terengganu

Charts Affected : Mal 6441
BA 3482

**PATON BANK LIGHT BUOY UNLIT
KERTIH, TERENGGANU WATERS**

Mariners are advised that Paton Bank light buoy is unlit. The details are as follows:

1. Name : Paton Bank
Position : Lat. 04° 32.670' N, Long. 103° 31.370' E
Light Characteristic : FL.R.5S

Mariners are advised to navigate with caution in the area.

(Ts. MUHAMMAD FADHLI BIN MAKHTAR)
for The Director General,
Marine Department Malaysia.
6th August 2023

