



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUARTERS, MENARA DIUS API
PO BOX 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



PENINSULAR NOTICE TO MARINERS NTM 186 / 2024

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Port Klang Waters

Charts Affected : MAL 5307
 BA 3945

**TAIL LIGHT BUOY RESTORED TO NORMAL
PORT KLANG**

Mariners are advised that Tail light buoy has been restored to normal. The details are as follow:

Name : **Tail**

Position : **Lat 03° 00.390' N**
 Long 101° 21.215' E

Light Characteristic : **Q.W** (North Cardinal Mark)

Mariners are advised to navigate with caution when in the vicinity.
This notice cancels NTM 81(T)/2024.

(EMIZUL FADLY MASDEK)
for The Director General,
Malaysia Marine Department.
24th September 2024.