



**MALAYSIA MARINE DEPARTMENT**  
**MARINE HEADQUARTERS**  
**P.O BOX 12, JALAN LIMBUNGAN**  
**42007 PELABUHAN KLANG**  
**SELANGOR DARUL EHSAN**  
**MALAYSIA**



**PENINSULAR NOTICE TO MARINERS    NTM 198(T)/2023**

Telefon           : 03-3346 7777    Emel               : [kpqr@marine.gov.my](mailto:kpqr@marine.gov.my)  
Faksimili       : 03-3168 5289    Laman Web      : <http://www.marine.gov.my>

Authority           : Director of Marine, Malaysia  
Position            : South China Sea, Kuantan Port  
Charts Affected   : MAL 6359  
                          BA 3482

**NDWT BREAKWATER 2Y LIGHT BEACON UNLIT**  
**KUANTAN PORT**

Mariners are advised that NDWT Breakwater 2Y light beacon is unlit. The details are as follows:

Name                : **NDWT Breakwater 2Y**  
Position            : **Lat. 03° 59.832' N, Long. 103° 26.081' E**  
                          (*Datum: WGS-84*)  
Light Characteristic : **FL.Y.2s**

Mariners are advised to navigate with caution when in the vicinity.

**(EMIZUL FADLY BIN MASDEK)**  
for The Director General,  
Marine Department Malaysia.  
1<sup>st</sup> September 2023

*Safer Ships, Secure Ports, Cleaner Seas*



CERTIFIED TO ISO 900:2015  
CERT. NO.: QMS 03602