



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUARTERS, MENARA DIUS API
PT 664, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS

NTM 199/2024

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Johor Waters, Kukup

Charts Affected : MAL 5123, MAL512
BA 2403

P2 LIGHT BUOY RE-PLACED IN POSITION JOHOR WATERS

Mariners are advised that P2 light buoy has returned to its position. The details are as follows:

Name : **P2**
Position : **Lat** 01° 17.28 ' N ,
Long. 103° 26.49' E (*Datum: WGS-84*)
Light
Characteristic : **FL.W.5s.**

Marines are advised to navigate with extra caution in the vicinity.
This notice cancels NTM 193(T0/2024).

(EMIZUL FADLY MASDEK)
for The Director General,
Malaysia Marine Department.
11th October 2024